

BRUST & ASSOCIATES

Engineers - Planners - Surveyors

1610 Diamond Drive
Anchorage, Alaska 99507
(907) 562-7878

SOILS LOG - PERCOLATION TEST

PERFORMED FOR: Bonnie Rumley DATE PERFORMED: 8/10/85

LEGAL DESCRIPTION: Lot 9B, Block 2 Stephenie Subd #2

DEPTH (FEET)		SLOPE	SITE PLAN
1	Fill		
2	Topsoil old ground surface		
3	Sand SW		
4	Clear Gravel GW		
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			

WAS GROUND WATER ENCOUNTERED? Yes


IF YES, AT WHAT DEPTH? 72"

SLOPE 0%

Reading	Date	Gross Time	Net Time	Depth to Water	Net Drop

PERCOLATION RATE _____ (minutes/inch)

TEST RUN BETWEEN _____ FT AND _____ FT



COMMENTS: Water was at the seasonal high water level

PERFORMED BY: S. Brust CERTIFIED BY: H. Brust DATE: 8/10/85

